




Volvo L 90 H

General features

Brand	Volvo
Subcategory	Wheel loader
Construction year	2019
operatingHours	6619
Condition	Used
General condition	Very good
ceMarking	1



Volvo L 90 H

Description

Volvo L 90 H Year of construction 2019 6614 Working hours New tires Pfreundt Wheigt installation Camera

Accessories